

Tel.: +39 040 375 5402/3 Fax.: +39 040 375 5404 e-mail: info@carso.co.uk www.carso.co.uk

Cod. Fisc. 90036690320 Partita IVA00316290329 Iscr. Reg. Imp. di Trieste No 10511

## **AMS-02 STAR TRACKER**

ENGINEERING CHANGE ORDER Page: 1/1

Date: September '09 Doc.: AST/ ECO004

Ver.: 1.1

## **ENGINEERING CHANGE ORDER**

Engineering Change Order Number ECO004

System AMICA Star Tracker

Subsystem ASTC - AMICA Star Cracker Camera

Part Name

Part Number 240.001

Serial Number 001

Description As per Non conformance Record Number

NCRN004, Reduce the height of the pins on the bottom of the STCC el. board (244.500). As precaution, electrically insulate the AST T bridge in the part under the video signal connection. Replace the final stage (op amp) of the amplification chain to make the system

functional.

Prepared by P.Trampus

Approved by P.Trampus

Validation (OK/NOK) OK

Report

Performed by F.Santarossa